

SPECIAL OPERATING CONDITIONS
K276FK PINECLIFFE, COLORADO
MOUNTAIN COMMUNITY TRANSLATORS, LLC
FCC FORM 350
DECEMBER 2010

Compliance with all operating conditions have been met under the terms of the construction permit, BPFT-20100831ACG, for K276FK Pinecliffe, Colorado, facility ID 157107.

See the answers to the conditions and referenced by condition number on the Construction Permit:

- 1) Permittee/Licensee will coordinate with other users of the site and will reduce power of cease operation as necessary to protect persons having access to the site, tower, or antenna from radiofrequency electromagnetic fields in excess of FCC guidelines.
- 2) Form 350 is being filed prior to normal program test operations.
- 3) Permittee/Licensee has performed radiofrequency electromagnetic (RF) field strength measurements throughout the transmitter site area to determine if there are any areas that exceed the FCC guidelines for human exposure to RF fields. Measurements were made with a Narda model 8718B measuring device. No areas were found to exceed the $200 \mu\text{W}/\text{cm}^2$ exposure limit for un-controlled areas at any point near the tower site. The site is fenced around the base of the towers, and posted with appropriate RF warning signs.